



TD05 28230-45000

Quality built aftermarket turbochargers

DESCRIPTION

Model
TD05-12G-6, TD05-14G, TD05-3, TD05H

Part No.
49178-02320, 49178-03122, 49178-03128
49178-02385, 49178-09620, 49178-81100
28230-45000, 28230-45100, 2823045000

OE Code
ME014878, ME014881

Engine
Hyundai D4DA;
Mitsubishi 4D34T, 4D34TI, 4D34-T44.MLF

Hyundai

Hyundai Mighty II / County with D4DA engine

Mitsubishi

Mitsubishi Fuso Commercial Canter 60 LWK with 4D34T engine

APPLICATIONS



ONLINE
Sale

FACTORY DIRECT!





 **DIRECT
REPLACEMENT**



K18 INCONEL ALLOY WHEELS





**TWO
YEARS WARRANTY**