



TD04V

49477-01203

Quality built aftermarket turbocharger chra

DESCRIPTION

Model

TD04V

Part No.

49477-01203, 49477-01214, 49477-01200
49477-01202, 4947701203, 4947701214
4947701200, 4947701202

OE Code

LR038322, LR022358, LR065510, LR038309
LR049592, 9906194170, BG9Q6K682CB
BG9Q6K682CC

Engine

SD4, TD4, DWI2C JLR
110KW 150PS 2179ccm; 120KW 163PS 2179ccm
140KW 190PS 2179ccm; 147KW 200PS 2179ccm

Land Rover

2014–2018 Land Rover Discovery Sport 2.2 D 4WD. 140KW, 190PS

2014–2018 Land Rover Discovery Sport 2.2 D 4WD. 110KW, 150PS

2010–2014 Land Rover Freelander 2 2.2 eD4. 110KW, 150PS

2010–2014 Land Rover Freelander 2 2.2 SD4 4x4. 140KW, 190PS

2006–2014 Land Rover Freelander 2 2.2 TD4 4x4. 110KW, 150PS

2006–2014 Land Rover Freelander 2 2.2 TD4 4x4. 115KW, 156PS

2007–2014 Land Rover Freelander 2 2.2 TD4 4x4. 112KW, 152PS

2006–2014 Land Rover Freelander 2 2.2 TD4 4x4. 118KW, 160PS

2011–2018 Land Rover Range Rover Evoque 2.2 eD4. 110KW, 150PS

2011–2018 Land Rover Range Rover Evoque 2.2 SD4. 140KW, 190PS

2011–2018 Land Rover Range Rover Evoque 2.2 TD4. 110KW, 150PS

APPLICATIONS

Jaguar

2011–2015 Jaguar XF 2.2 D. 120KW, 163PS

2011–2015 Jaguar XF 2.2 D. 140KW, 190PS

2012–2015 Jaguar XF 2.2 D. 147KW, 200PS

2012–2014 Jaguar XF Sportbrake 2.2 D. 120KW, 163PS

2012–2014 Jaguar XF Sportbrake. 147KW, 200PS

A PPLICATIONS



ONLINE
Sale

FACTORY DIRECT!





 **DIRECT
REPLACEMENT**



K18 INCONEL ALLOY WHEELS





**TWO
YEARS WARRANTY**